



ENGINEERING TECH BULLETIN

EZ-Pull 2 Service Kits to Replace Original EZ-Pull Pin Cartridges

Beginning January 1, 2019, Hutchens Industries will be supplying our EZ-Pull 2 (EZP2) service kits in place of the original EZ-Pull replacement pin cartridges. The EZP2 is our newest pin system and if service should ever be necessary repair will be simpler since individual parts can be replaced. The EZ-Pull 2 is now our standard lock pin system and has superseded the original EZ-Pull on all sliders. The original EZ-Pull cartridges will no longer be available.



Example of Original EZ Pull Cartridge



Equivalent EZP2 Assembled Cartridge



Un-assembled EZP2 Service Kit Example

These service kits will be bagged and shipped un-assembled. Each bag will be identified with a label containing a QR code and web address that can be utilized to obtain drawings and installation instructions specific to each service kit.

A typical label is shown below.



ENGINEERING TECH BULLETIN EZP2 Service Kits for EZ-Pull Cartridges	Released 01-22-2018	REV DATE:01/27/21	SHEET 1 of 3
		REV: D	DWG NO. ETB 2018-8



ENGINEERING TECH BULLETIN

EZ-Pull 2 Service Kits to Replace Original EZ-Pull Pin Cartridges

EZ Pull Cartridge to EZIP2 Service Kit Cross-reference

ORIGINAL EZ-Pull PIN CARTRIDGE PART NO.	EZIP2 SERVICE KIT NO.	EZIP2 INSTALLATION PROCEDURE NO.	SLIDER SERIES
18945-01	29558-02	29576	H8901/H8931
18945-03	29558-01	29576	H8901/H8931
18945-05	29558-04	29576	H8901/H8931
19033-01	29559-02	29659	H9801/H9811
19033-03	29559-01	29659	H9801/H9811
19033-09	29559-03	29659	H9801/H9811
19299-01	29559-07	29677	NEWAY NSH SLIDES FRONT PIN
19299-03	29559-06	29677	NEWAY NSH SLIDES FRONT PIN
19300-01	29559-09	29648	NEWAY NSH SLIDES REAR PIN
19300-03	29559-08	29648	NEWAY NSH SLIDES REAR PIN
19395-03	29571-03	29561	NEWAY NSB SLIDES
19395-04	29571-03	29561	NEWAY NSB SLIDES
20563-01	29558-06	29623	MERITOR RHP
20564-01	29571-01	29563	MERITOR RHP 11
20565-01	29571-02	29718	MERITOR RHP 11
20635-01	29573-02	29685	H9851/H9861
20635-02	29573-01	29685	H9851/H9861
20852-01	29574-01	29719	WILSON PROP 44" IBC Z-FRAME
20852-02	29574-02	29719	WILSON PROP 44" IBC Z-FRAME
21007-01	29573-04	29681	DANA AIR RIDE
21007-02	29573-04	29681	DANA AIR RIDE
21007-03	29573-03	29681	DANA AIR RIDE
21007-04	29573-03	29681	DANA AIR RIDE
21360-01	29559-05	29645	DANA SR1VK200/201
21360-02	29559-05	29645	DANA SR1VK200/201
21360-03	29559-04	29645	DANA SR1VK200/201
21360-04	29559-04	29645	DANA SR1VK200/201
23424-01	29558-05	29645	DANA ADVANTAGE SLIDE FRONT PIN
23424-02	29558-05	29645	DANA ADVANTAGE SLIDE FRONT PIN
23425-01	29558-07	29801	DANA ADVANTAGE SLIDE REAR PIN
23425-02	29558-07	29801	DANA ADVANTAGE SLIDE REAR PIN
23757-01	29571-04	29701	DANA ADVANTAGE SLIDER REAR LH
23757-02	29571-05	29701	DANA ADVANTAGE SLIDER REAR RH
23794-01	29571-06	29713	DANA ADVANTAGE SLIDER FRONT LH
23794-02	29571-07	29713	DANA ADVANTAGE SLIDER FRONT RH



EZ Pull Cartridge to EZP2 Service Kit Cross-reference

Should you require additional information or have any questions regarding this bulletin please contact Hutchens Industries at 1-800-654-8824.

ENGINEERING TECH BULLETIN EZP2 Service Kits for EZ-Pull Cartridges	Released 01-22-2018	REV DATE:01/27/21	SHEET 3 of 3
		REV: D	DWG NO. ETB 2018-8